

# 2022 Hyundai Tucson

Elite NX4.V1 MY22 AWD

**\$30,870**

Drive Away



**Enquire Now**

Scan the QR code below  
for more information



|                                                                                                             |                                                                                                                                  |                                                                                                                       |                                                                                                                                                    |
|-------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------|
|  Year<br><b>2022</b>      |  Body<br><b>SUV</b>                           |  Colour<br><b>White Cream</b>      |  Transmission<br><b>7 SP Sports Automatic<br/>Dual Clutch</b> |
|  Engine<br><b>1.6 L</b>   |  Kilometres<br><b>57355 Kms</b>               |  Stock #<br><b>U54829</b>          |  Power<br><b>132</b>                                          |
|  Drive Type<br><b>AWD</b> |  Fuel System<br><b>4 Cyl Direct Injection</b> |  VIN #<br><b>KMHJC81BWNU173281</b> |  Reg #<br><b>CBZ530</b>                                       |

Bay City Auto Group Franks ton

WHERE ARE YOU LOCATED? We are located in FRANKS TON. We are right next to Eastlink M3. Only 37klms from the CBD in the southeast bayside area.



**Frankston Kia**

**Call us on (03) 9122 8749**

140 Dandenong Road West, Frankston, VIC, 3199

Every effort has been made to ensure the accuracy of the information above, however, errors may occur.